


Site Photos

Exhibit 2: Current Condition Site Images



Photos 1, 2, & 3. Manzanita Canyon is blighted with introduced plants; degraded, un-vegetated, slopes; trash accumulations and illegal dumping; and large volumes of storm water runoff from the surrounding streets. The above photo shows the storm drain outfall from the Triangle Property into the Manzanita Canyon streambed.

Site Photos



Photo 4. Homeless encampments are common within the Triangle Property. The Living Lab (yellow building) is in the background.



Photo 5. The intersection of Thorn St. (potential site of Green Street infrastructure) with the canyon streambed (left) and Living Lab (background).



Photo 6. The current steep, eroded, and hazardous social trail from the top of the Triangle Property down to the Living Lab and canyon entrance.